
City of Baltimore Wet Smoke and Dyed	Page 1 of 2	
Sewershed: Gwynns Falls	Company: Savin	Date: 4/23/2009
Test to be performed: Smoke Dyed Water X	Ground Condition: Dry ✓ Damp ☐ Wet ☐	Supervisor: <u>JAW</u>
Manhole_ID: S03K 015MH	Test ID: <u>D1032-002005</u>	Notification Made: NA (Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Manhole	S03K015MH
14.60000038			Dye Test Visible	@ IR, 1/16 GPM
14.60000038	04		Infil Runner	
16.5			Dye Test Visible	@ IR & FC,4 GPM
16.5	03	10	Infil Runner	
16.5	08	09	Fracture Circumferential	
19.39999962			Dye Test Visible	@ IR, 1/2 GPM
19.39999962	07		Infil Runner	
21.39999962			Dye Test Visible	@ IR, 1/2 GPM
21.39999962	08		Infil Runner	
25.20000076			Abandoned Survey	NO MORE DYE VISIBLE

City of Baltimore Wet Smoke and Dyed	Page 2 of 2	
Sewershed: Gwynns Falls	Company: Savin	Date: 4/23/2009
Test to be performed: Smoke Dyed Water X	Ground Condition: Dry ✓ Damp □ Wet □	Supervisor: JAW
Manhole_ID: S03K_015MH	Test ID: <u>D1032-002005</u>	Notification Made: NA (Residents, Fire, 311)